



Bundesministerium  
für Digitales  
und Verkehr


## DAC4EU Data Communication Tests

Roland Hess, OWITA GmbH



# Phase I – Brief Look at Phase I


## Tested Communication Concepts



# Phase I – Brief Look at Phase I

## Communication Tests in Standstill of Wagons

Measurements of physical communication channels (wired, radio)



### Result of the channel measurements ✓

- Communication with modern communication systems possible (2-wire bus, powerline, radio)
- Slight differences between couplers regarding channel quality identified

Performance measurements with communication systems:

- WiFi,
- CAN-FD,
- Powerline-PLUS

Datarates: 1 – 6 Mbit/s

Packetrates: 330 – 2600 Packets/Second

Latency (RTT): 6 – 200 ms

*(Train with 12 wagons)*

### Results of the performance Measurements: ✓

- Requirements for the transferred information rate could be reached by tested systems (WiFi, CAN-FD Powerline-PLUS)
- Differences of latency, datarate and packetrate depending on communication system (no dependency of coupler type)


Official report: Phase I: <https://bmdv.bund.de/SharedDocs/DE/Artikel/E/dak-demonstrator.html>

# Stress Tests (Standstill)


SPE

→ **Evaluation of the max./sufficient segment length:** Communication established in available train segment of 5 wagons

→ **Test with stub lines (up to 30m):** Insertion of a stub line caused a short link down -> link up event (may cause integrity fail)  
**Reason:** The change of the physical communication channel leads to a new channel estimation procedure (0.5 – 1s)



→ **Test with bridge lines (up to 30m):** Insertion of a bridge line caused a short link down -> link up event  
**Reason:** The change of the physical communication channel leads to a new channel estimation procedure




# Stress Tests (Standstill)

Powerline




→ Evaluation of the max. segment length without repeater slave


Forward Distance 3:




Forward Distance 4:



Forward Distance 3:



Forward Distance 2:




# Stress Tests (Standstill)

Powerline

→ Long segment length in train composition with ballast wagons

Forward Distance 2:



- All devices could be identified
- No communication problems found with insertion of a long segment
- Segment with ballast wagons equipped with 2x10mm<sup>2</sup> cable (EDDP proposed cable with twisted pair wires)

# Phase II – Communication Tests on Train Operation

## Tests on Tracks

### Demonstration of operational functions:

#### 1. Train initialisation process to identify:

- Count of wagons
- Sequence of wagons (UIC wagon numbers)
- Direction of wagons

#### 2. Train integrity during train operation

- Communication availability to the last wagon

### Availability of the communication systems


- Monitoring of packet error rates and temporary failures of the communication systems



# Phase II – Communication Tests on Train Operation

## Test Setup in Phase IIa with 13 Wagons

- Only changes of the position of the wagon groups between tests
- No changes inside wagon groups possible => Couplers always connected to the same opposite coupler partner





# Operational Function


## Train Initialisation

### Detection of wagon count and sequence (SPE and WiFi):

- Scan of the train via ICMP (Internet Control Message Protocol) to detect the count of the wagons
- Sorted wagon list derived from power values of the 110 V<sub>DC</sub> powerline



Alternative solution:  
Topology detection using  
TRDP (Train Redundancy  
Data Protocol)



### Detection of wagon count and sequence in Powerline-PLUS:

- The Powerline-Plus generates a list of the wagons from internal detection function
- Sequence is derived from the signal runtime (with a minimum distance of 5 meters in the DAC4EU test setup between modems)

```
##### TOPOLIST #####
TTD status      : COMPLETE
Topology size   : 17
Displayed entries : 17
-----
Entry  Addr   Wagon ID  MPD [ms]
-----
0      0x0001  0x00000000C  0
1      0x0002  0x000000001  505
2      0x0003  0x00000000E  685
3      0x0004  0x00000000D  869
4      0x0005  0x000000002  921
5      0x0006  0x000000006  1093
6      0x0007  0x00000000B  1226
7      0x0008  0x000000004  1408
```

# Operational Function

## Train Initialisation Test Result



### Detection of wagon count and sequence (used in SPE and WiFi):

- Detection of wagon count (by ICMP) always functional as long as communication connection to the last wagon could be established
- Detection of the sequence based on power measurement in 40% of the initialisations wrong, reasons:
  - => Inaccurate power sensors,
  - => No synchronized power measurement with changing power over time
  - ➔ *For SPE and WiFi the method defined in ETB (TRDP, IEC61375-2-5) should be considered*
- Detection of the wagon orientation (based on current flow direction) was working successfully.

### Detection of wagon count and sequence in Powerline-PLUS:

- Generated list with **amount and sequence of wagons** was **correct** in all initialisation processes

# WiFi Communication

## WiFi Results – Tests on Communication Faults

Table of the WiFi communication results:

Test run	T1	T2	T3	T4	T5	T6	T7	T8	T9	T10
Integrity fails	1	3	0	broken after 30 minutes	27	129	213	135	111	268
PER (%)	8,40	14,24	0	63,94	6,67	13,05	7,84	34,04	6,86	38,88

\* Integrity fails are incremented on communication interruption for more than 900 ms

**Note:** Tested WiFi system **different** to the EDDP WiFi on short list

Two different fault scenarios could be seen for WiFi:

→ Communication **interruption of few packets** (several 100 ms) up to **several seconds**

→ Communication **interruption** for a **long period** (> 2 minutes)

→ Later examinations showed that location of fault connections were changing between a few wagon connections. Some connections had a stable link without fails.

# WiFi Communication

## WiFi Results – Conclusions

- **Long** communication **interruptions** caused by special device mode (ACC) and **can be avoided** by using other smart technologies
- **Shorter** communication **interruptions** caused probably by **interferences** and partly by **instable devices**

⇒ **Radio communication** outside the coupler should not be considered due to the following aspects:

- Interferences can cause burst packet fails,
- Unsafe initialisation process: Links may jump over one or two wagons, especially in reflective environments. Detection of correct sequence and wagon count could not be guaranteed.

Removed from EDDP short list  
⇒ **Testing of WiFi discontinued!**

# Powerline PLUS Communication

## Powerline Communication Tests

Table of the Powerline-PLUS communication results:

Test run	T1	T2	T3	T4	T5	T6	T7	T8	T9	T10	T11
Integrity fails	0	0	0	0	0	0	0	0	0	0 no measures	0
PER	0%	0%	0%	0%	0%	0%	0.03%	0.02%	0.01%	no measures	0.02%

→ **Stable communication over all tests**

→ Tests after T6 showed occurrence of single packet fails (no burst errors). The latency increased as well. This happened in timeslots where packet errors appeared

→ PLC Integrated **integrity check** and additional integrity check (ICMP) **without malfunction**

→ Monitoring of the  $110V_{DC}$  supply voltage of the powerline showed few interruptions. This can lead depending on the interruption to a single packet fail on the powerline system

# Single Pair Ethernet Communication

## SPE – Communication Tests Phase II

Table of the SPE communication results:

	T1	T2	T3	T4	T5	T6	T7	T8	T9	T10	T11
Integrity fails*	0	0	0	0	0	1	83	16	86	19	1
PER (%)	0.008	0.107	0.027	0.033	0.015	0.411	2.762	1.267	2.341	0.624	0.042


\* Integrity fails are incremented on communication interruption for more than 900 ms

→ **Massive communication problems started** at tests with **T7**


→ Assumption, that one or several wagon connections caused the problems

→ With test T8 a new function was integrated to detect the point of failures


Histogram of communication losses and duration T7



Histogram of communication losses and duration T8



Histogram of communication losses and duration T11




# Contact Monitoring

## Monitoring with Logic Analyzer



- Tests with logic analyzer at four couplers
- Massive measurement errors (very short peak interruptions with a duration of 1  $\mu$ s and below)
- Nevertheless, few interruptions on one coupler could be seen with intervals from 3 ms to 19 ms




# Contact Monitoring

## Monitoring with Current Loop Through all Wagons

Measurement idea: Monitoring of all coupler connections on communication line (with location tracking of the interruption)


- Second two wire line connected in the wagon boxes to get connected line through the train
- Resistor installed in each wagon between the two wires
- Measurement of the current with an oscilloscope (by shunt resistor) should show the length and location of interruptions

### Expected result:



### Result:

- **No (long) interruption** on communication pins could be seen
- Sporadic **distorsions** on the line, but very **short pulses**
- Distorsions can often be seen after **train vibrations**, but also in standstill
- Assumption: Crosstalk from the powerline to the data bus line at specific wagons






# Contact Monitoring

## Monitoring on a Specific Wagon

Measurement: Scope monitoring of the 110 V<sub>DC</sub> powerline contacts



### Result:

- In a few cases a contact failure on the powerline pins could be seen (2 ms)

→ The Powerline-PLUS system works in the DAC4EU train composition well:

→ The **detection** of the **position worked well**

→ Robustness: **Stable communication to the last wagon**

→ Using the Repeater **Forward Distance of 2** always **worked**. A **higher forward distance of** repeater slave **caused problems** and may be **reached** on using **EDDP proposed cabling** (integrated cables with constant wave resistance)

→ SPE-Communication is less reliable:

→ **Problems** regarding the **stability** of the communication must be investigated. In some testcases the **contact problems** at the couplers seems to be the **problem**, in latest tests distorsions on the communication line may lead to packet losses

→ Robustness (distorsions): Adaption to filters inside the single pair ethernet device may lead to better resilience

→ If **contact failures** in the couplers appear for **more** than **several 100  $\mu$ s**, SPE loses the synchronisation and needs to **reinitialize** the link for **500 ms -3 seconds**. This is an **issue** for **safety relevant functions!**



Bundesministerium  
für Digitales  
und Verkehr

**Thank You!**

